

Control Module	Type	PR-Code	Protocol	3G	HFP	PBAP	A2DP	rSAP	SOP	Notes
Part Number										
1K8-035-730	UHV-Standard <i>Nokia HT-3</i>	-	DDP	No	Yes	???	Yes	No	???	> 1K8-035-730-B
1K8-035-730-A	UHV-Standard <i>Nokia HT-3</i>	-	DDP	No	Yes	???	Yes	No	???	<b>Note #2</b>
1K8-035-730-B	UHV-Standard <i>Nokia HT-3</i>	9ZU	DDP	No	Yes	???	Yes	No	27/2008	> 1K8-035-730-C
1K8-035-730-C	UHV-Standard <i>Novero HT-3</i>	9W2/9ZG	DDP/BAP	No	Yes	???	Yes	No	22/2008	> 1K8-035-730-D
1K8-035-730-D	UHV-Standard <i>Novero HT-3</i>	9W2/9W8/9ZF 9ZG/9ZU	DDP/BAP	No	Yes	???	Yes	No	52/2008	-
1K8-051-730-A	Volk-L <i>Novero HT-3</i>	-	DDP	No	Yes	???	Yes	No	???	<b>Note #1</b>
1K8-051-730-B	Volk-L <i>Novero HT-3</i>	-	DDP	No	Yes	???	Yes	No	???	<b>Note #1</b>
120-035-729	UHV-Standard <i>Temic 2P7X</i>	9W3/9W4/9W8	DDP	No	Yes	???	???	No	???	> 120-035-729-B
120-035-729-A	UHV-Standard <i>Harman/Becker 2P8X</i>	9W9	BAP	No	Yes	???	???	No	Dez 09	> 120-035-729-D
120-035-729-B	UHV-Standard <i>Harman/Becker 2P7X</i>	9W3/9W4/9W8	DDP	No	Yes	???	???	No	???	-
120-035-729-C	UHV-Standard <i>Harman/Becker 2P8X</i>	9W3/9W4 9W8/9W9	BAP	No	Yes	???	???	No	22/2009	> 120-035-729-E
120-035-729-D	UHV-Standard <i>Harman/Becker 2P8X</i>	9W3/9W4 9W8/9W9	BAP	No	Yes	???	???	No	Dez 09	> 120-035-729-C
120-035-729-E	UHV-Standard <i>Harman/Becker 2P8X</i>	9W3/9W4 9W8/9W9	BAP	No	Yes	???	???	No	53/2009	-
3C0-035-730	UHV-Premium <i>Nokia HT-2</i>	9ZW	DDP	No	No	???	???	Yes	???	> 3C0-035-730-A
3C0-035-730-A	UHV-Premium <i>Nokia HT-2</i>	9ZW	DDP	No	No	???	???	Yes	???	> 3C0-035-730-B
3C0-035-730-B	UHV-Premium <i>Nokia HT-2</i>	9ZW	DDP	No	No	???	???	Yes	???	-
3C8-035-730	UHV-Premium <i>Nokia HT-2</i>	9ZU/9ZW	BAP	No	???	???	???	???	???	> 5N0-035-730-A
3C8-035-730-A	UHV-Premium <i>Novero HT-4</i>	9ZU/9ZW	BAP	Yes	Yes	Yes	Yes	Yes	22/2010	> 5N0-035-730-D
3C8-035-730-B	UHV-Premium <i>Novero HT-4</i>	9W4/9ZU/9ZZ	BAP	Yes	Yes	Yes	Yes	Yes	22/2011	-
3C8-035-730-C	UHV-Premium <i>Novero HT-4</i>	9W4/9ZU/9ZZ	BAP	Yes	Yes	Yes	Yes	Yes	22/2012	-
3C8-035-730-D	UHV-Premium <i>Novero HT-5</i>	9IC/9W4/9ZG 9ZU/9ZZ	BAP	Yes	Yes	Yes	Yes	Yes	22/2013	WiFi Support
3C8-035-730-E	UHV-Premium <i>Novero HT-5</i>	9IC/9W4/9ZG 9ZU/9ZZ	BAP	Yes	Yes	Yes	Yes	Yes	22/2014	WiFi Support
5K0-035-730	UHV-Standard <i>S1nn/Parrot CK5050+</i>	9W7/9W8	BAP	???	???	???	???	???	Feb 11	-
5K0-035-730-A	UHV-High <i>S1nn/Parrot CK5050+</i>	9ZA/9ZF	BAP	???	???	???	???	???	52/2010	-
5K0-035-730-B	UHV-High <i>S1nn/Parrot CK5050+</i>	9ZB/9ZN	BAP	???	???	???	???	???	???	(> 7P6-035-730-E)
5K0-035-730-D	UHV-High <i>S1nn/Parrot CK5050+</i>	9ZB/9ZN	BAP	???	???	???	???	???	45/2011	(> 7P6-035-730-J)
5K0-035-730-F	UHV-High <i>S1nn/Parrot CK5050+</i>	9ZA	BAP	???	???	???	???	???	37/2011	-
5N0-035-730	UHV-Premium <i>Nokia HT-2</i>	9ZU/9ZW	DDP/BAP	No	???	???	???	Yes	???	> 3C8-035-730
5N0-035-730-A	UHV-Premium <i>Nokia HT-2</i>	9ZA/9ZU	DDP/BAP	No	???	???	???	Yes	???	> 5N0-035-730-B
5N0-035-730-B	UHV-Premium <i>Novero HT-2</i>	9ZB/9ZU	DDP/BAP	No	No	No	No	Yes	22/2009	> 5N0-035-730-C
5N0-035-730-C	UHV-Premium <i>Novero HT-2</i>	9ZU/9ZW	DDP/BAP	No	No	???	No	Yes	40/2009	-
5N0-035-730-D	UHV-Premium <i>Novero HT-4</i>	9ZU/9ZZ	BAP	Yes	Yes	Yes	Yes	Yes	45/2010	> 3C8-035-730-B
5P0-862-335	UHV-Standard <i>Harman/Becker 2P5X</i>	9W2/9W4 9W8/9W9	DDP	No	Yes	???	???	No	-	> 5P0-862-335-A <b>Note #3</b>
5P0-862-335-A	UHV-Standard <i>Harman/Becker 2P5X</i>	9W2/9W4 9W8/9W9	DDP	No	Yes	???	???	No	???	> 5P0-862-335-B <b>Note #3</b>
5P0-862-335-B	UHV-Standard <i>Harman/Becker 2P5X</i>	9W2/9W4 9W8/9W9	DDP	No	Yes	???	???	No	???	<b>Note #3</b>
5P0-862-335-C	UHV-Standard <i>Harman/Becker 2P5X</i>	9W2/9W4 9W8/9W9	DDP	No	Yes	???	???	No	25/2005	> 120-035-729
5P0-862-335-D	UHV-Standard <i>Harman/Becker 2P7X</i>	9W9	BAP	No	Yes	???	???	No	-	-
7E0-035-730	UHV-High <i>Novero HT-2</i>	9ZB	BAP	???	???	???	???	???	???	-
7E0-035-730-A	UHV-High	9W6	BAP	???	???	???	???	???	45/2010	> 5K0-035-730-A
7E0-035-730-B	UHV-High	9ZN	BAP	???	???	???	???	???	???	> 5K0-035-730-B
7E0-035-730-C	UHV-High	9ZB	BAP	???	???	???	???	???	???	> 5K0-035-730-B
7E0-035-730-D	UHV-High	9ZA	BAP	???	???	???	???	???	???	> 5K0-035-730-A
7H0-035-730	UHV-???	???	???	???	???	???	???	???	???	-
7L6-035-730	UHV-???	???	???	???	???	???	???	???	???	-
7L6-035-730-C	UHV-???	???	???	???	???	???	???	???	???	-
7P6-035-730-B	UHV-High <i>S1nn/Parrot CK5050+</i>	9ZB	BAP	???	???	???	???	???	???	> 5K0-035-730-B
7P6-035-730-C	UHV-Standard <i>S1nn/Parrot CK5050+</i>	9W7/9W8	BAP	???	???	???	???	???	22/2010	-
7P6-035-730-D	UHV-High <i>S1nn/Parrot CK5050+</i>	9ZA/9ZF	BAP	???	???	???	???	???	22/2010	-
7P6-035-730-E	UHV-High	9ZB/9ZN	BAP	???	???	???	???	???	???	> 5K0-035-730-D
7P6-035-730-F	UHV-Standard <i>S1nn/Parrot CK5050+</i>	9W7/9W8	BAP	???	???	???	???	???	22/2011	> 5K0-035-730-E
7P6-035-730-G	UHV-Standard	9W6/9ZA/9ZF	BAP	???	???	???	???	???	22/2011	> 5K0-035-730-F
7P6-035-730-H	UHV-Standard	9W4	BAP	???	???	???	???	???	22/2011	(> 3C8-035-730-B)
7P6-035-730-J	UHV-Standard	9ZB	BAP	???	???	???	???	???	22/2012	-
7P6-035-730-L	UHV-Standard	9ZA	BAP	Yes	Yes	Yes	Yes	???	22/2012	-

#### Abbreviations:

3G = 3G / UMTS Network Support  
A2DP = Advanced Audio Distribution Profile (Media/Audio Files on your Phone play on your Car's Radio/Stereo)  
BAP = Operating and Display Protocol (newer Instrument Clusters, Volkswagen Models with **white** Displays)  
BT = Bluetooth (Column Refers to the Version of the supported Bluetooth Standard)  
DDP = Display Data Protocol (older Instrument Clusters, Volkswagen Models with **red** Displays)  
DUN = Dial-Up Network Profile (Internet Connection via Bluetooth Module in the Vehicle)  
HFP = Hands Free Profile (Phone still logged in, Vehicle/Bluetooth Module acts mostly as Headset)  
PBAP = Phone Book Access Profile  
rSAP = Remote-SIM Access Profile (Phone inactive/standby, Bluetooth Module takes over all Functions)  
SOP = Start Of Production (Value refers to the Calendar Week of each Year, e.g. 22/2011 = CW 22 in 2011 - Dates may vary depending on Model)  
TBD = To Be Determined (Supported but exact Version unknown at this Point)  
WPAN = Wireless Personal Area Network (Vehicle/Telephone Module provides Internet Access for other Devices)

#### Notes:

**Note #1:** Official Retrofit Part Number 1K0-051-437.  
**Note #2:** Not compatible with VW Touareg 2 (7P).  
**Note #3:** No RN5510/Columbus Support.